



## Media Converter Setup Instructions

**1)** Plug A.C. adapters into associated equipment, including Laptop and Media converter




**2)** Ensure the Power LED is illuminated.




**3)** Connect the Media Converter to the laptop using a standard Ethernet cable.




**4)** Check position of middle switch on media converter. Make sure it is set to MDI-X if using the cable shipped from CTS. If using your own cable and it is a crossover (most aren't), set this switch to MDI.




**5)** Ensure LNK LED is illuminated.



**6)** ON LINE light should be illuminated at this point.



**7)** Make sure the "Terminator" switch is set to "ON." Use the coax cable that shipped from CTS to connect the media converter directly to the wall plate. If there is a switch on the wall plate, make sure it is set "Local" and that all other switches on other wall plates are set to "Remote." If your old computer had a "T" connector with a terminator cap, DO NOT use it with this system.



**8)** Now you can enter the DisplayLink program. At this time, the RX and TX lights will be illuminated.

**9)** There should be no errors upon entering DisplayLink. If you receive any errors such as "Scoreboard has lost its connection," repeat the previous instructions.